

ROLE WITH RIGHTS REPORT



ROLE	ASSIGNED RIGHTS
Admin	Set All Parameters,Add User,Edit User,Manage User,Add Role,Edit Role,View Audit Trail,Print Audit Trail,View Activity Log
Administrator	Set All Parameters,Add User,Edit User,Manage User,Add Role,Edit Role,Add Department,Edit Department,Add Calibration Standards,Edit Calibration Standards,Add Instruments,Edit Instruments,Add Product,Edit Product,Activate / Deactivate,Cubicle Setting,Test,Calibration,Set Recalibration,View Report(Self),Reprint Report(Self),View All Report,Reprint All Report,Verify Report,View Audit Trail,Print Audit Trail,Add Equipment,Edit Equipment,View Activity Log,Area Setting,Content Type,Verify Balance
HQ	Cubicle Status
SuperAdmin	Cleaner,Discard IPC,Cleaner,Discard IPC,Set All Parameters,Add User,Edit User,Manage User,Add Role,Edit Role,Add Department,Edit Department,Add Calibration Standards,Edit Calibration Standards,Add Instruments,Edit Instruments,Add Product,Edit Product,Activate / Deactivate,Cubicle Setting,Test,Calibration,Set Recalibration,View Report(Self),Reprint Report(Self),View All Report,Reprint All Report,Verify Report,View Audit Trail,Print Audit Trail,Add Equipment,Edit Equipment,View Activity Log,Area Setting,Content Type,Verify Balance
Superviosor	Add Calibration Standards,Edit Calibration Standards,Add Instruments,Edit Instruments,Add Product,Edit Product,Activate / Deactivate,Cubicle Setting,Test,Calibration,Set Recalibration,View Report(Self),Reprint Report(Self),View All Report,Verify Report,View Audit Trail,Print Audit Trail,Add Equipment,Edit Equipment,View Activity Log,Content Type,Verify Balance