

Role With Rights Report

ROLE	ASSIGNED RIGHTS
Admin	Set All Parameters,Add User,Edit User,Manage User,Add Role,Edit Role,Add Department,Edit Department,Add Calibration Standards,Edit Calibration Standards,Add Instrument,Edit Instrument,Add Product,Edit Product,Activate / Deactivate,Cubicle Setting,View Report(Self),Test,Calibration,Set Recalibration,Verify Report,Reprint Report(Self),View All Report,Reprint All Report,Add Equipment,Edit Equipment,View Audit Trail,Print Audit Trail,Stage,Area Setting,Media,View Activity Log,Batch Reuse
admin2	Set All Parameters,Add User,Add Role,Edit Department,Add Calibration Standards,Edit Instrument,Activate / Deactivate,View Report(Self),Test,Calibration,Verify Report,Reprint Report(Self),Edit Equipment,View Audit Trail,Print Audit Trail
adminn	Set All Parameters,Add Department,Add Calibration Standards,Add Instrument,Add Product,Edit Product,Activate / Deactivate,Verify Report,View All Report,Reprint All Report
B_Reuse	Set All Parameters,Add User,Edit User,Manage User,Add Role,Edit Role,Add Department,Edit Department,Add Calibration Standards,Edit Calibration Standards,Add Instrument,Edit Instrument,Add Product,Edit Product,Cubicle Setting,View Report(Self),Test,Calibration,Set Recalibration,Verify Report,Reprint Report(Self),View All Report,Reprint All Report,Add Equipment,Edit Equipment,View Audit Trail,Print Audit Trail,Stage,Area Setting,Media
Batch Reuse role	Set All Parameters,Add User,Add Role,Edit Role,Add Calibration Standards,Edit Calibration Standards,Add Product,Edit Product,View Report(Self),Test,Verify Report,Reprint Report(Self),Edit Equipment,Stage,Area Setting
CS traniee	Add Calibration Standards,Edit Calibration Standards,Add Instrument,Edit Instrument,Add Product,Edit Product,View Report(Self),Test,Calibration,Set Recalibration,Verify Report,Reprint Report(Self),View All Report,Add Equipment,Edit Equipment,View Audit Trail,Print Audit Trail,Area Setting,View Activity Log

Role With Rights Report

ROLE	ASSIGNED RIGHTS
manager	Set All Parameters,Add User,Edit User,Manage User,Add Role,Edit Role,Add Department,Edit Department,Add Calibration Standards,Edit Calibration Standards,Add Instrument,Edit Instrument,Add Product,Edit Product,Activate / Deactivate,Cubicle Setting,View Report(Self),Test,Calibration,Set Recalibration,Verify Report,Reprint Report(Self),View All Report,Reprint All Report,Add Equipment,Edit Equipment,View Audit Trail,Print Audit Trail,Stage,Area Setting,View Activity Log,Batch Reuse
QA	Add User,Edit User,Edit Instrument
QC	Set All Parameters,Add User,Edit User,Manage User,Add Role,Edit Role,Add Department,Edit Department,Add Calibration Standards,Edit Calibration Standards,Add Instrument,Edit Instrument,Add Product,Edit Product,Activate / Deactivate,Cubicle Setting,View Report(Self),Test,Calibration,Set Recalibration,Verify Report,Reprint Report(Self),View All Report,Reprint All Report,Add Equipment,Edit Equipment,View Audit Trail,Print Audit Trail,Stage,Area Setting,Media,View Activity Log
SOfware2	Set All Parameters,Add Calibration Standards,View Report(Self),Test
SuperAdmin	Alert Setting,Set All Parameters,Add User,Edit User,Manage User,Add Role,Edit Role,Add Department,Edit Department,Add Calibration Standards,Edit Calibration Standards,Add Instrument,Edit Instrument,Add Product,Edit Product,Activate / Deactivate,Cubicle Setting,View Report(Self),Test,Calibration,Set Recalibration,Verify Report,Reprint Report(Self),View All Report,Reprint All Report,Add Equipment,Edit Equipment,View Audit Trail,Print Audit Trail,Stage,Area Setting,Media,View Activity Log,Batch Reuse
test 2	Set All Parameters,Add User,Edit User,Stage,Area Setting

Role With Rights Report

ROLE	ASSIGNED RIGHTS
test1	Set All Parameters,Add User,Edit User,Cubicle Setting,View Report(Self),Test,Calibration,Reprint Report(Self),Stage,Area Setting
TESTER	Set All Parameters,Add User,Add Role,Edit Role,Add Calibration Standards,Edit Calibration Standards,Add Product,Edit Product,View Report(Self),Test,Verify Report,Edit Equipment,Stage,Area Setting
TESTING	Set All Parameters,Add User,Add Role,Edit Role,Add Calibration Standards,Edit Calibration Standards,Add Product,Edit Product,View Report(Self),Test,Verify Report,Reprint Report(Self),Edit Equipment,Area Setting